

URGENT Field Safety Notice

MR Systems: Patient support floor plate cage installation issue leading to potential for tipping

16-May-2024

This document contains important information for the continued safe and proper use of your equipment.

Please review the following information with all members of your staff who need to be aware of the contents of this communication. It is important to understand the implications of this communication.

Please retain this letter for your records.

Dear Customer,


Philips has identified an issue with certain MR room cage installations where the patient support (table) floor plate may have been incorrectly installed during construction of the MR suite. This may cause the table to become dislodged from the floor and potentially cause harm to the patient and/or operator. Note: The MR system will perform per its intended use. This issue is not related to a device malfunction. Refer to section 3 for potentially impacted systems. This URGENT Field Safety Notice is intended to inform you about:

1. What the problem is and under what circumstances it can occur

The patient support floor plates for MR systems may not have been anchored to the floor according to Philips requirements causing the patient support to become unstable with the potential for tipping (see Figure 1). This movement can inadvertently lead to harm to the patient and/or operator under certain circumstances.

There have been 25 complaints reported to Philips associated with the patient support floor plate issue for MR systems and no reports of harm or injury as of February 2024.

Figure 1: Example of patient support floor plate which shows upward movement of the patient support in the picture on the right.



2. Hazard/harm associated with the issue.


If the patient support were to become dislodged from the floor, the risk to patients or operators may include physical harm from falling from the table, pinching of extremities or other body parts between the patient support and system or floor, and/or delayed diagnosis.

3. Affected products and how to identify them.

Identification of Impacted Systems:

Potentially impacted systems can be identified by the Model and REF number (REF). The Model name and REF can be found on the system label, as indicated by the red boxes in Figure 2.

Figure 2. System label Example
All MR systems

Example System Label Location	Model	REF number
		781296
		781196
	Achieva 1.5T	781343
	Achieva 1.5T Conversion	781346
	Achieva 1.5T Initial system	781283
		781178
		781177
		781277
		781278
		781344
	Achieva 3.0T	781345
	Achieva 3.0T for PET	781477
	Achieva 3.0T TX for PET	781479
		781153
	Achieva XR	781253
	Enterprise 1.5T	781145
	Evolution upgrade 3.0T	782143
	GYROSCAN ACS-NT	78107
	GYROSCAN T10-NT	78108
	GYROSCAN T5	78104
	GYROSCAN T5-NT	78106
		781396
		781315
		782115
		781341
		782140
Ingenua 1.5T	782101	
	781261	
Ingenua 1.5T CX	781262	
Ingenua 1.5T S	781347	
	781377	
	781342	
Ingenua 3.0T	782103	
Ingenua 3.0T CX	781271	

	782105
	782133
	782139
	781359
Ingenia Ambition S	782108
	781356
	782109
Ingenia Ambition X	782138
	781357
	782106
Ingenia Elition S	782137
	782136
	781358
	782107
Ingenia Elition X	782119
Intera 0.5T Standard	781101
Intera 1.0T Omni/Stellar	781102
Intera 1.0T Power/Pulsar	781103
	781195
Intera 1.5T	781295
Intera 1.5T Achieva IT Nova	781175
Intera 1.5T Achieva Nova	781172
Intera 1.5T Achieva Nova-Dual	781173
Intera 1.5T Explorer/Nova Dual	781108
Intera 1.5T Master/Nova	781106
Intera 1.5T Omni/Stellar	781104
Intera 1.5T Power/Pulsar	781105
Intera 1.5T R11	781170
Intera 3.0T Quasar Dual	781150
Intera Achieva 1.5T Pulsar	781171
Intera CV	781107
MR 5300	782110
MR 7700	782120
	781260
SmartPath to dStream for 1.5T	782146
	782112
	781270
SmartPath to dStream for XR and 3.0T	782113
	782129


Please locate the system label of your impacted MR system according to the following steps:

1. Enter the Technical Room
2. Locate the system label (see Figure 3) which can be found on the cabinet door
3. Locate the model and reference number on the system label (see Figure 4)

Figure 3: Example Front door of cabinet



Figure 4: system label



Intended Use:

Philips Magnetic Resonance (MR) systems are Medical Electrical Systems indicated for use as a diagnostic device. This MR system enables trained physicians to obtain cross-sectional images, spectroscopic images and/or spectra of the internal structure of the head, body or extremities, in any orientation, representing the spatial distribution of protons or other nuclei with spin.

4. Actions that should be taken by the customer / user in order to prevent risks for patients or users.

- A. Customers can continue using the identified systems in accordance with the intended use.
- B. As a reminder: When using the system, follow section *Patient Support and Tabletop* in the Instructions For Use (IFU) provided with your system: *The safe working load as labeled on patient support and trolley is based on the sum of the maximum allowable patient weight and the mass of accessories and coils. The weights mentioned are equal to the safe working load*
 - *The maximum weight load allowed for horizontal and vertical movement of the tabletop on the patient support and the maximum allowed weight load of the table top on the FlexTrack in Table 1 below are taken from their respective IFU:*

Table 1. Safe Working Load per applicable IFU

Product name	Product number	Trolley safe working load	Patient support safe working load
Achieva 1.5T,	781296, 781196,781343	150 kg, 330 lbs	250 kg, 550 lbs
Achieva 1.5T Conversion	781346, 781283		
Achieva 1.5T Initial system	781178		
Achieva 3.0T,	781177, 781277,781278, 781344, 781345		
Achieva 3.0T for PET	781477		
Achieva 3.0T TX for PET	781479		
Achieva XR,	781253, 781153		
Enterprise 1.5T	781145		
Evolution upgrade 3.0T	782143		
GYROSCAN ACS-NT	78107		
GYROSCAN T10-NT	78108		

GYROSCAN T5	78104		
GYROSCAN T5-NT	78106		
Intera 0.5T Standard	781101		
Intera 1.0T Omni/Stellar	781102		
Intera 1.0T Power/Pulsar	781103		
Intera 1.5T	781295, 781195		
Intera 1.5T Achieva IT Nova	781175		
Intera 1.5T Achieva Nova	781172		
Intera 1.5T Achieva Nova-Dual	781173		
Intera 1.5T Explorer/Nova Dual	781108		
Intera 1.5T Master/Nova	781106		
Intera 1.5T Omni/Stellar	781104		
Intera 1.5T Power/Pulsar	781105		
Intera 1.5T R11	781170		
Intera 3.0T Quasar Dual	781150		
Intera Achieva 1.5T Pulsar	781171		
Intera CV	781107		
Ingenia 1.5T	781396,781315, 782115, 781341, 782101,782140		
Ingenia 1.5T CX	781261, 781262		
Ingenia 1.5T S	781347		
Ingenia 3.0T	782103, 781377, 781342		
Ingenia 3.0T CX	781271, 782105		
Ingenia Ambition S	782133, 782139, 781359, 782108		
Ingenia Ambition X	781356, 782109, 782138		
Ingenia Elition S	781357, 782106, 782137		
Ingenia Elition X	782136, 781358, 782107, 782119		
MR5300	782110		
MR 7700	782120		
SmartPath to dStream for 1.5T	781260, 782112, 782146		
SmartPath to dStream for XR and 3.0T	781270, 782113, 782129		

- C. If the patient’s weight is at (or near) the maximum load mentioned above, take care that:
- They do not sit on the end of the tabletop opposite the bore entrance.
 - From their seated position along the edge of the tabletop, they do not hop down from their sitting position while the support is at its highest position.
- D. If the patient support has any unexpected movement and / or becomes unstable (dislodged movement between the system and the floor), immediately stop use and contact your Philips service representative for interim support.
- E. Circulate this notice to all users of this device so that they are aware of the potential issue.
- F. Please display attached ‘Advisory’ with your system(s); ensure the notice is in a place likely to be seen/viewed by operators.

- G. Please complete and return the attached acknowledgment form to Philips MR promptly upon receipt and no later than 30 days from receipt via email to: pd.cnr@philips.com.

5. Actions planned by Philips to correct the problem.


Philips is providing this Field Service Notice (FSN) Letter which contains recommendations for continued use of the systems referenced in Section 4.

A Philips representative will contact you to schedule time for an FSE to visit your site to perform an inspection regarding the patient support stability. (Reference FCO 78100570).

Please be assured that maintaining a high level of safety and quality is our highest priority. If you need any further information or support concerning this issue, please contact your local Philips representative.

This notice has been reported to the appropriate Regulatory Agencies.

Sincerely,



David Hanly
Head of Quality, Philips Magnetic Resonance (MR)

URGENT Field Safety Notice Response Form

Reference: Patient Support for MR systems (FCO 78100570)

Instructions: Please complete and return this form to Philips promptly and no later than 30 days from receipt. Completing this form confirms receipt of the Urgent Field Safety Notice, understanding of the issue, and required actions to be taken.

Customer/Consignee/Facility Name: _____

Street Address: _____

City/State/ZIP/Country: _____

Customer Actions:

- A. Customers can continue using the identified systems in accordance with the intended use.
- B. Follow the instructions provided in section 4 of the Field Safety Notice Letter.
- C. Circulate this notice to all users of this device so that they are aware of the issue.
- D. Please display attached 'Advisory' with your system(s); ensure the notice is in a place likely to be seen/viewed by operators.

We acknowledge receipt and understanding of the accompanying Urgent Field Safety Notice and confirm that the information from this notice has been properly distributed to all users that handle the affected systems.

Name of person completing this form:

Signature: _____

Printed Name: _____

Title: _____

Telephone Number: _____

Email Address: _____

Date (DD / MMM / YYYY): _____

Please complete and return the attached acknowledgement form to Philips MR via email to: pd.cnr@philips.com.

**Advisory Notice - MR Systems:
Patient support floor plate cage installation issue leading to potential for tipping**

As a reminder: When using the system, follow section *Patient Support and Tabletop* in the Instructions For Use (IFU) provided with your system: *The safe working load as labeled on patient support and trolley is based on the sum of the maximum allowable patient weight and the mass of accessories and coils. The weights mentioned are equal to the safe working load.*

- *The maximum weight load allowed for horizontal and vertical movement of the tabletop on the patient support and the maximum allowed weight load of the tabletop on the FlexTrack in Table 1 below are taken from their respective IFU:*

Table 1. Safe Working Load per applicable IFU

Product name	Product number	Trolley safe working load	Patient support safe working load
Achieva 1.5T,	781296, 781196,781343	150 kg, 330 lbs	250 kg, 550 lbs
Achieva 1.5T Conversion	781346, 781283		
Achieva 1.5T Initial system	781178		
Achieva 3.0T,	781177, 781277,781278, 781344, 781345		
Achieva 3.0T for PET	781477		
Achieva 3.0T TX for PET	781479		
Achieva XR,	781253, 781153		
Enterprise 1.5T	781145		
Evolution upgrade 3.0T	782143		
GYROSCAN ACS-NT	78107		
GYROSCAN T10-NT	78108		
GYROSCAN T5	78104		
GYROSCAN T5-NT	78106		
Intera 0.5T Standard	781101		
Intera 1.0T Omni/Stellar	781102		
Intera 1.0T Power/Pulsar	781103		
Intera 1.5T	781295, 781195		
Intera 1.5T Achieva IT Nova	781175		
Intera 1.5T Achieva Nova	781172		
Intera 1.5T Achieva Nova-Dual	781173		
Intera 1.5T Explorer/Nova Dual	781108		
Intera 1.5T Master/Nova	781106		
Intera 1.5T Omni/Stellar	781104		
Intera 1.5T Power/Pulsar	781105		
Intera 1.5T R11	781170		
Intera 3.0T Quasar Dual	781150		
Intera Achieva 1.5T Pulsar	781171		
Intera CV	781107		

Ingenia 1.5T	781396,781315, 782115, 781341, 782101,782140	250kg, 550 lbs	250kg, 550 lbs
Ingenia 1.5T CX	781261, 781262		
Ingenia 1.5T S	781347		
Ingenia 3.0T	782103, 781377, 781342		
Ingenia 3.0T CX	781271, 782105		
Ingenia Ambition S	782133, 782139, 781359, 782108		
Ingenia Ambition X	781356, 782109, 782138		
Ingenia Elition S	781357, 782106, 782137		
Ingenia Elition X	782136, 781358, 782107, 782119		
MR5300	782110		
MR 7700	782120		
SmartPath to dStream for 1.5T	781260, 782112, 782146		
SmartPath to dStream for XR and 3.0T	781270, 782113, 782129		

If the patient’s weight is at (or near) the maximum load mentioned above, take care that:

- They do not sit on the end of the tabletop opposite the bore entrance.
- From their seated position along the edge of the tabletop, they do not hop down from their sitting position while the support is at its highest position.

If the patient support has any unexpected movement and / or becomes unstable (dislodged movement between the system and the floor), immediately stop use and contact your Philips service representative for interim support.