



Abbott Laboratories
1921 Hurd Drive
Irving, Texas 75038 USA

Single Registration Number (SRN):
US-MF-000017778

Urgent Field Safety Notice Urgent Product Correction

Immediate Action Required

Date Issued January 16, 2024

Product

Product Description	List Number	Serial Number	UDI
Alinity s System	06P16-01	Refer to Attachment A	

Explanation

Abbott has identified two potential issues that may be exhibited when operating the Alinity s System software version 2.8.2 (List Number 04U76-17) and prior. Abbott is releasing Alinity s System software version 2.9.0 (LN 04U76-18) to prevent these potential issues and improve the system.

Issue 1

This issue only impacts Alinity s System instruments that are integrated with a Laboratory Automation System (LAS).

Misassigned sample pipettor aspiration locations at the LAS can cause results to be wrongly attributed to the incorrect unique sample identifier (SID). There is one occurrence of this issue due to an incomplete LAS calibration. Maintenance and Diagnostics (M&D) procedure 7140 *Sample Pipettor LAS Calibration (FSE Logon)* has been updated with Alinity s System software version 2.9.0 to require the use of a barcoded calibration tool by the Abbott Field Service Engineer (FSE) when calibrating sample pipettors at the LAS aspiration positions.

Issue 2

Pipettor positioning may be off target if a pipettor probe is not straight or homed correctly due to unintended contact between the pipettor or pipettor probe with another component during instrument operation. Sample pipettor probe positioning that is skewed 1.5 – 2.0mm can cause inaccurate pipetting without generating a *Robotics and sensor Message code (5000-5999)*. Pipettor probe positioning off target more than 2.0mm will result in a Message code being generated and tests will be sent to exception. Test results are not impacted by mispositioned pipettor probes that may be off target less than 1.5mm. There are no occurrences attributed to incorrect results due to misaligned pipettor probe positioning within the 1.5 - 2.0mm range. The Alinity s System software version 2.9.0 includes pipettor probe straightness and homing checks to verify optimum pipettor positioning during run initialization.

Alinity s System software version 2.9.0 will be available worldwide as Abbott receives approval to distribute the updated software within each country. Once the country-specific regulatory approvals are obtained, your Abbott representative will be scheduling a mandatory upgrade of your Alinity s System(s) to install software version 2.9.0.

Impact on Donor/Patient Results

An incorrect LAS aspiration location calibration can cause misassigned test results, i.e., the result assigned to the SID originated from another SID onboard the instrument.

A bent or mispositioned sample pipettor probe off target 1.5 -2.0mm has the potential to adversely affect pipetting accuracy and cause incorrect test results (false positive).

Necessary Actions

Continue to operate and maintain the Alinity s System as described within the *Alinity s System Operations Manual*. There are no additional necessary actions to be taken by customers.

M&D 7140 *Sample Pipettor LAS Calibration (FSE Logon)* is only performed by trained Abbott representatives. If erratic results or poor precision is observed, follow the recommended corrective actions stated in the *Alinity s System Operations Manual*, Section 10, Troubleshooting, Observed Problems.

A bent or misaligned pipettor probe can be detected by performing the M&D 7110 *Pipettor Calibration and Straightness* procedure. The procedure is primarily performed by Abbott representatives during troubleshooting and quarterly preventive maintenance (PM) service visits.

If you have forwarded the Alinity s System to other laboratories, please inform them of this Product Correction and provide them a copy of this letter.

Complete and return the Customer Reply Form.

Please retain this letter for your laboratory records.

Contact Information

If you or any of the health care providers you serve have questions regarding this information, U.S. Customers please contact Customer Service at 1-877-4ABBOTT (available 24 hours a day, 7 days a week). Customers outside the U.S., please contact your local area Customer Service.

Adverse reactions or quality problems experienced with the use of this product may be reported to the FDA's MedWatch Adverse Event Reporting program at <http://www.fda.gov/MedWatch/report.htm>, by phone (1-800-332-1088), or fax (1-800-FDA-0178).

If you have experienced any patient or user injury associated with this Field Action, please immediately report the event to your local area Customer Service.
