

Siemens Healthcare Diagnostics GmbH, SHS EMEA CEET QT, Siemensstrasse 90,
1210 Vienna

Name M.A. Roland Ertl
 Department SHS EMEA CEET QT
 Mobile +43 (664) 8011738274
 E-mail roland.re.ertl@siemens-healthineers.com
 Date October 10, 2023
 Document Ref# POC 23-018.A.OUS

Urgent Field Safety Notice:

**RAPIDPoint® 500 Blood Gas System / RAPIDPoint® 500e Blood Gas System
 Perhexiline Maleate and Atomoxetine Hydrochloride Interference on Sodium Measurement**

To whom it may concern,

Our records indicate that your facility may have received the following products:

Table 1. Affected Products

Product Description	Siemens Material Number (SMN)	Unique Device Identification (UDI-DI)
RAPIDPoint 500 Blood Gas System	10492730 (USA)	00630414589169
	10696855 (CHINA)	00630414590851
	10696857 (JAPAN)	00630414590868
	10697306 (ROW)	00630414590844
RAPIDPoint 500e Blood Gas System	11416751 (USA)	00630414286143
	11416752 (CHINA)	00630414286150
	11416754 (JAPAN)	00630414286167
	11416755 (ROW)	00630414286174

Note: All analyzer serial numbers are affected

Reason for Urgent Field Safety Notice

The purpose of this communication is to inform you of a potential issue with the products indicated in Table 1 above and provide instructions on actions that your laboratory must take.

Siemens Healthcare Diagnostics Inc. has determined that two drugs, Perhexiline Maleate and Atomoxetine Hydrochloride, may interfere with sodium results that are reported on the RAPIDPoint 500 and RAPIDPoint 500e Blood Gas Systems indicated in Table 1.

Tables 2 below summarizes the effect on samples that contain Perhexiline Maleate and Atomoxetine Hydrochloride, respectively.

Table 2. Interference Observed on Sodium Results on the RAPIDPoint 500/500e Blood Gas Systems

Substance	Concentration Tested (mg/dL)	Level of Interference on Sodium (mmol/L)
Perhexiline Maleate	≥ 0.01	> + 2.0
Atomoxetine Hydrochloride	≥ 0.04	> + 2.0

Siemens Healthcare is aware of two complaints associated with this issue. There have been no reports of adverse events.

Risk to Health

The presence of perhexiline maleate and atomoxetine hydrochloride has the potential to cause erroneously elevated sodium results which may lead to unrecognized hyponatremia and/or the inappropriate treatment of hypernatremia. Hyponatremia is associated with significant symptoms including nausea, malaise, headache, lethargy, obtundation and eventually seizures, coma, and respiratory arrest. Mitigations include the geographically restricted use of perhexiline maleate (which is mostly used in Australia and New Zealand), the short time-interval testing needs to occur after drug dosing for atomoxetine hydrochloride due to its short half-life, correlation of results with other electrolyte results such as chloride, historical sodium results, and the clinical history of the patient.

– Actions to be Taken by the Customer

- Please review this letter with your Medical Director to determine the appropriate course of action, including for any previously generated results, if applicable.
- Complete and return the Field Correction Effectiveness Check Form attached to this letter within 30 days.
- If you are a distributor, please ensure your customers receive this UFSN letter.
- Please retain this letter with your system's Operator's Guide and forward this letter to those who may have received this product.

Siemens Healthcare Diagnostics will be revising the RAPIDPoint 500 and RAPIDPoint 500e System Operator's Guide with information on the interfering substances. Once the revisions are completed, they will be available in Siemens Healthineers Document Library.

We apologize for the inconvenience this situation may cause. If you have any questions, please contact your Siemens Healthineers Customer Care Center or your local Siemens Healthineers technical support representative.

Sincerely yours,

Siemens Healthcare Diagnostics GmbH

Signature:



*Electronically signed by: Roland Ertl
Reason: I am approving this document
Date: Oct 5, 2023 11:53 GMT+2*

Email: roland.re.ertl@siemens-healthineers.com

i.A. Roland Ertl, MA

Signature:



*Electronically signed by: THOMAS
HUFNAGL
Reason: I have reviewed this document
Date: Oct 9, 2023 14:46 GMT+2*

Email: thomas.hufnagl@siemens-healthineers.com

i.A. Mag. Thomas Hufnagl