



URGENT: FIELD ADVISORY NOTICE

Issue Date: 29 APRIL 2024

FSN #: 3014162263-04/19/24-001-R

PRODUCT: Optima and Prestige Coil Systems

PURPOSE: Discoloration along delivery pusher component

Who may be affected: Distribution agents and hospital staff including safety officers, purchasing agents, pharmacists, radiology staff, and physicians including but not limited to interventional radiologists, neuro interventional radiologists, endovascular neurosurgeons, and interventional neurologists.

Dear Partners,

The purpose of this letter is to advise affected customers that Balt USA is voluntarily recalling some lots of the Optima and Prestige Coil Systems due to the possibility that the distal, 3 cm radiopaque (RO) marker may not be visible under fluoroscopy. Since January 2024, Balt USA has received six (6) global complaints related to this issue all sourced to a supplier's improper line clearance. To date, Balt has not received any report of patient harm related to any of these complaints.

This hazard presents minimal risk to patient safety and is unlikely to cause adverse health consequences, as it is common practice to assess proper coil placement while visualizing the RO marker and the coil mass before detachment. In addition, the operator can remove the implicated coil system and use a new coil system if the RO marker is not visible. Therefore, any adverse consequence associated with the use of the device with the RO marker not visible would be limited to a modest increase in procedure time with no additional immediate or long-term health consequences.

To prevent any product issue with the potential issue of the RO marker not being visible, Balt USA has decided to (voluntarily recall)/(voluntarily initiate a Field Service Corrective Action for) the affected Optima and Prestige Coil System lots. The affected lots were manufactured between August and September 2023. Refer to Attachment 1 for the list of affected finished good lots.

As an alternative to returning the affected product, Balt USA suggests that product from lots with potentially affected product can be tested for the presence of the RO marker using an available fluoroscopy imaging equipment (prior to a clinical procedure). The image is achieved by removing the sealed pouch from the box then taking the fluoroscopic image of coil system within the sealed pouch. If the image contains the RO marker, as exemplified from **Figure 1**, complete the "Notice of Receipt" (refer to the annex on page 3) indicating the verified results. Send the completed "Notice of Receipt" to Balt Extrusion at FSCA_QA@baltgroup.com. Return the product back to your inventory with no further action required. If the image does not contain the RO marker, contact Balt Extrusion SAS at FSCA_QA@baltgroup.com to process the return of the product.




Figure 1. Representative image taken of the coil system inside of the sealed pouch with visible RO marker located 3 cm from the proximal end of the coil.

BALT USA

T: +1 949.788.1443

F: +1 949.788.1444

29 Parker
Irvine, CA 92618 • USA

www.baltgroup.com



If product return is desired, follow the instructions from the pertinent section as a distribution agent or as a hospital staff.

Procedure to be applied by distribution agents:

- Inform customers about this notice.
- Return to Balt Extrusion SAS the applicable products and lots from the provided list.
 - Collect and put in quarantine the Optima or Prestige Coil System concerned by this recall and then return them to Balt Extrusion SAS through the usual "RMA" (Return Materials Authorization) procedure by contacting our Customer Service department.
 - Keep Balt USA informed of the status of products concerned by this recall.
 - Fulfill the "Notice of Receipt" (refer to the annex on page 3) then return it to Balt Extrusion SAS via the indicated contact.
- Contact Balt Extrusion SAS at FSCA_QA@baltgroup.com for any additional information.

Procedure to be applied by hospital staff:

- Inform your hospital staff including safety officers, purchasing agents, pharmacists, radiology staff, and head of healthcare centers, as well as any other person, if deemed necessary.
- Return to Balt Extrusion SAS the applicable products and lots from the provided list.
 - Collect and put in quarantine the Optima or Prestige Coil System concerned by this recall and then return them to Balt USA through the usual "RMA" (Return Materials Authorization) procedure by contacting our Customer Service department or confirm the presence of RO marker as described above.
 - Keep Balt Extrusion SAS informed of the status of products concerned by this recall.
 - Fulfill the "Notice of Receipt" (refer to the annex on page 3) then return it to Balt Extrusion SAS via the indicated contact.
- Contact Balt Extrusion SAS at FSCA_QA@baltgroup.com for any additional information.

Any adverse reactions or quality issues experienced in conjunction with or as a result of the affected product may be reported to the FDA's MedWatch Adverse Event Reporting program. Reporting can be done through the online reporting portal or by downloading, completing, and then submitting FDA Form 3500 (health professional) or 3500B (consumer/patient) to MedWatch: The FDA Safety Information and Adverse Event Reporting Program.

Online Reporting Portal: https://www.accessdata.fda.gov/scripts/medwatch/index.cfm?action=reporting_home

Mailing Address: MedWatch, Food and Drug Administration, 5600 Fishers Lane, Rockville, MD 20852

FAX: (800) 332-0178

Should you require any additional information about this medical device recall, do not hesitate to contact our Quality Department.

Contact:

Quality Department

✉: FSCA_QA@baltgroup.com

Balt Extrusion SAS

Rue du Fonds des Aulnes

95160 Montmorency

FRANCE

We apologize for this inconvenience and thank you for your cooperation in this regard.

Thomas Colson
VP, Global Quality Assurance

Claus Freyinger
VP, Global Regulatory, Clinical, Medical Affairs

BALT USA

T: +1 949.788.1443

F: +1 949.788.1444

29 Parker
Irvine, CA 92618 • USA

www.baltgroup.com



Annex: Notice of Receipt Ref. # 3014162263-12/23/23-001-R

RETURN THE COMPLETED RECEIPT BY: FAX: +22 1 39 89 46 41/ MAIL: Rue du Fonds des Aulnes | 95160 Montmorency| FRANCE
(Quality Department) / **E-MAIL: FSCA_QA@baltgroup.com**

1. Field Safety Notice (FSN) information	
FSN Reference number*	3014162263-12/23/23-001-R
FSN Date*	29 April 2024
Product/ Device name*	Optima and Prestige Coil Systems
Product Code(s) and Lot Numbers	Please see Attachment 1

2. Distributor/Importer Details	
Company Name*	
Account Number	
Address*	
Shipping address if different to above	
Contact Name*	
Title or Function	
Telephone number*	
Email*	

3. Return acknowledgement to Sender	
Email	FSCA_QA@baltgroup.com
Postal Address	Balt Extrusion SAS Rue du Fonds des Aulnes, 95160 Montmorency - FRANCE
Deadline for returning the Distributor/Importer reply form*	14 Business Days

4. Distributors/Importers (Tick all that apply)		
<input type="checkbox"/>	*I confirm the receipt, the reading and understanding of the Field Safety Notice.	Distributor/Importer to complete or enter N/A
<input type="checkbox"/>	We confirm that, after verification of our stock and the stocks of our users, we declare having no physical Optima or Prestige Coil System product(s) concerned by this recall procedure listed within Attachment 1	N/A



<input type="checkbox"/>	We opt to not return the product(s) concerned by this recall. We have confirmed the presence of the RO marker for the affected Optima and/or Prestige Coil Systems listed within Attachment 1 .	Distributor/Importer to document the information in the table on page 5 .
<input type="checkbox"/>	We declare as having physical Optima and/or Prestige Coil System product concerned by this recall listed within Attachment 1. We have indicated the lot number, model/size and volume of Optima and/or Prestige Coil System product(s) concerned by this recall and will return the affected units to Balt Extrusion SAS.	Distributor/Importer to enter quantity and date on page 5
<input type="checkbox"/>	I have identified customers that received or may have received this device	
<input type="checkbox"/>	I have attached customer list	
<input type="checkbox"/>	I have informed the identified customers of this FSN	Date of communication:
<input type="checkbox"/>	I have received confirmation of reply from all identified customers	
<input type="checkbox"/>	I have returned affected devices - enter number of devices returned and date complete.	Complete page 5
Print Name*		Distributor/Importer print name here
Signature*		Distributor/Importer sign Here
Date *		

Mandatory fields are marked with *

It is important that your organisation takes the actions detailed in the FSN and confirms that you have received the FSN. Your organisation's reply is the evidence we need to monitor the progress of the corrective actions.

